

CERTIFICATION by CUSTODIAN of RECORDS

Tucson Police Department Crime Laboratory 270 S. Stone Avenue Tucson, AZ 85701-1917

I hereby certify that these documents are a true and correct copy of the periodic maintenance* for the Intoxilyzer 8000 Serial Number
80-00/163 maintained by the Tucson Police Department
Crime Laboratory pursuant to the requirements of the Arizona Department
of Public Safety for a quality assurance program.
A quality assurance specialist (QAS) tested the instrument on the following
dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2,
for a 0.100AC solution are 0.090AC to 0.110AC.
Date: 05/05/11 Cal 1 0.099 AC Cal 2 0.098 AC
Between the dates of 04/07/2011 and 05/05/2011 the instrument was operating properly and accurately.
Between the dates of $04/07/2011$ and $05/05/2011$
the instrument was operating properly and accurately.
The instrument was taken out of service for repair on
The instrument was returned to service on
///
Cly Stu
Cheryl K. Straub
Choryr R. Bulduo
05/10/2011
05/10/2011
ADPS QAS Permit # 33408 SUBSCRIBED AND SWORN to before me this, day of
ADPS QAS Permit # 33408 SUBSCRIBED AND SWORN to before me this
ADPS QAS Permit # 33408 SUBSCRIBED AND SWORN to before me this
ADPS QAS Permit # 33408 SUBSCRIBED AND SWORN to before me this
ADPS QAS Permit # 33408 SUBSCRIBED AND SWORN to before me this

*Includes documents specified in A.A.C. R13-10-104.A.5

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

EXHIBIT G-4

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD QUALITY ASSURANCE PROCEDURE

5.10.2011

QA SPECIALIST Cheryl Straub AGENCY Tucson	Police Department
DATE 05/05/2011 TIME 06:3	9
QA SPECIALIST Cheryl Straub agency Tucson Date $05/05/2011$ Time 06.3 Intoxilyzer serial # $80-001163$ Location TEI	4m 3
() 1. Display reads "PUSH BUTTON TO START"	
DIAGNOSTIC TESTS	
() 1. Clock time check. () 2. Date check.	
OPERATIONAL TESTS	
1. Alcohol-free subject test result 0. 000 2. Error recognition logic system functioning. Not a Successfully Completed Test Sequence pr 3. Proper sample recognition system. Not a Successfully Completed Test Sequence pr Deficient sample printed. 4. Standard Calibration Check standard 0. /00 Result: 0. 098 AC	inted inted
Instrument is operating properly and accurately. YES $ u$	NO
COMMENTS	
SIGNATURE Chy Tue	

DPS Form Exh G-4 (Rev. 05-01)

Serial Number: 80-001163

05/05/2011

06:40:33

Standard Lot#: 719919

Last Changed By: S. CIONE #50616 QAS: C. STRAUB #50772 TUCSON PD

Operator: C. STRAUB #50772

TUCSON PD

Subject: SQAP, SQAP DOB: 11/11/1111

Weight: 111 Sex: F

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	06:41:27
Diagnostic Test	Pass	06:41:54
Air Blank	0.000	06:42:21
0.100 Cal Check	0.099	06:42:40
Air Blank	0.000	06:43:10
Subject Test	0.000	06:43:30
Air Blank	ABT*	06:43:37
Air Blank	0.000	06:44:05

^{*}Sequence Aborted

storage devices of the Tucson Police Department.

Not a Successfully Completed Test Sequence

Serial Number : 80-001163

06:44:09

Standard Lot#: 719919

Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772

TUCSON PD

05/05/2011

Operator: C. STRAUB #50772

TUCSON PD

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F Weight: 111

15 Minute Deprivation Period? Yes

 Test
 g/210L
 Time

 Air Blank
 RFI*
 06:44:41

 Air Blank
 IPS**
 06:44:49

*RFI Detect

**Improper Sample

Not a Successfully Completed Test Sequence

124

Serial Number: 80-001163

05/05/2011

06:44:54

Standard Lot#: 719919 Last Changed By: S. CIONE #50616 QAS: C. STRAUB #50772 TUCSON PD Operator: C. STRAUB #50772 TUCSON PD

Subject: SQAP, SQAP DOB: 11/11/1111

Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	06:45:42
Diagnostic Test	Pass	06:46:10
Air Blank	0.000	06:46:37
0.100 Cal Check	0.098	06:46:56
Air Blank	0.000	06:47:26
Subject Test	0.054*	06:50:34
Air Blank	0.000	06:51:07
Air Blank	0.000	06:51:34
Subject Test	XXX**	06:51:54
Air Blank	0.000	06:52:29

^{*}Deficient Sample

Begin new deprivation period

Not a Successfully Completed Test Sequence

^{**}Invalid Sample

Serial Number: 80-001163

05/05/2011

06:52:52

Standard Lot#: 719919

Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772

TUCSON PD

Test	g/210L	Time
Air Blank	0.000	06:53:20
Cal Check	0.098	06:53:38
Air Blank	0.000	06:54:09

Operator's Signature

EXHIBIT G-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

134 5.10.2011

STANDARD CALIBRATION CHECK PROCEDURE

QA Sp	ecial	ist Charyl Straub AGENCY Tucson Police Department 5/05/2011 TIME 06:39 TSerial # 80-001163 Location TEAM 3
DATE	_05	105/2011 TIME 06:39
Intox	ilyzeı	r Serial # <u>80-001/63</u> Location <u>TEAM 3</u>
(V)	1.	Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0/OOAC.
		Pour a standard alcohol concentration solution NA AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach $34^{\circ}\text{C} \pm 0.2^{\circ}\text{C}$
(V)	2.	Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
		Intoxilyzer 8000 display reads "PUSH BUTTON TO START" Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
	4.	Air blank completed.
	5.	Calibration check completed. Test results 0. 099 AC.
	6.	Air blank completed.
(V)	7.	Air blank completed. Calibration check completed. Test results 0. 099 AC. Air blank completed. Remove printed record. Attach the record to the completed checklist.
SIGNA	vi.	Clif Str

DPS Form Exh G-2 (Rev. 05-01)

Serial Number: 80-001163

05/05/2011

06:39:02

Standard Lot#: 719919

Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772

TUCSON PD

Test	g/210L	\mathtt{Time}
2	5	
Air Blank	0.000	06:39:29
Cal Check	0.099	06:39:48
	0.033	00.09.10
Air Blank	0.000	06:40:18

Operator's Signature